

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Twin Sc. "LOCHAVON" Report GLs. No. 60050

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

FIRST ENTRY

When due

- ✓ K100A1 "With Freeboard"
"Carrying Bean or similar oil in Forward Centre, and Wing Tunnel Tanks"
- ✓ 1 Dk. and Shelter dk., 3rd deck except in No.4 hold, 4th dk. in Nos.2 and 3 holds.
- ✓ Cell.DB 408' 1574t, Tanks at Centre and sides of tunnel 635t, FPT 68t, APT 141t.
- ✓ FK, 7BH(Coll.BH to Shelter dk., 5BH to 2nd dk., 1BH to 3rd dk.).
pt.cem., pt.asp., Lloyd's A & CP.
- ✓ B 170', F 48'.
- ✓ O.L. 498'.



© 2021
Lloyd's Register
Foundation

W 500-0101