Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11.

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circular 1687 and the requisite details of the survey have been entered herein.

Index Nos. of items examined. †	Signature of Surveyor.	Place.	Date.
All	E.E. Brimblecombe.	Cardiff	20th May, 1937.

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

(i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and

(ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor E.E. Brimblecombe. *Place* Cardiff. *Date* 20th May, 1937.

Signature E.E. Brimblecombe.

Date 20th May, 1937.

† Insert "all" in case of a complete survey.

24.5.37

Fee £5-0-0

Number of Visits 3.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.

Rpt. C 11 (a). CARDIFF Freeboard Annual No. 503.

Lloyd's Register of Shipping.

MAY 21 1937

REPORT ON ANNUAL LOAD LINE SURVEY.

Name of Ship S.S. "QUARRINGTON COURT" Official Number 160614 Port of Registry London

Place of Survey Cardiff. Dates of Survey 18, 19 & 20/5/37 Date of last Load Line Survey Issued 5/6/36.

PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs. Necessary.	Repairs. Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
1. Exposed on freeboard deck.			
Coamings, their stays and stiffeners ...	Good		
Beams ...	"		
Fore and afters ...	none		
*Covers ...	Good except — 81 renewed & 5 part renewed.		19 & 20/5/37.
*Tarpaulins (State number per hatchway)	Good (3)		
*Cleats and battens ...	Good		
Lashings and their fittings ...	"		
Wedges ... (Is supply, including spares, adequate ?)	" Yes.		
2. Exposed on superstructure decks, including raised quarter decks.			
Coamings, their stays and stiffeners ...			
Beams ...			
Fore and afters ...			
*Covers ...			
*Tarpaulins (State number per hatchway)			
*Cleats and battens ...			
Lashings and their fittings ...			
Wedges ... (Is supply, including spares, adequate ?)			
3. Within superstructures not intact or not protected by Class I closing appliances.			
Coamings ...			
Beams ...			
Fore and afters ...			
Covers ...			
Tarpaulins (State number per hatchway)			
Cleats and Battens ...			
Wedges ... (Is supply, including spares, adequate ?)			

*Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (ii)).

10m.3.37. T

© 2020 Lloyd's Register Foundation

REP. "C.11." 7.A.No 503.

Items examined.	Condition in which found.	Repairs. Necessary.	Repairs. Date effected.
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	Good ✓		
Closing arrangements	"		
5. To spaces below decks of superstructures which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	Good		
Closing arrangements	"		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	Good ✓		
7. Within partially enclosed superstructures.			
Closing arrangements	none ✓		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddley openings, their covers and fastenings	Good ✓		
Skylights, their fastenings, covers and lashings	"		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	Good ✓		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	✓ ✓		
11. Within partially enclosed superstructures.			
Doors and fastenings	none ✓		
12. **FLUSH BUNKER SCUTTLES** and chain attachments	none ✓		
13. **COMPANIONWAYS**, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	Good ✓		

Items examined.	Condition in which found.	Repairs. Necessary.	Repairs. Date effected.
14. **CLOSING APPLIANCES FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS.**			
Forecastle	Open ✓		
Bridge, fore end...	✓		
Bridge, after end	✓		
Poop	✓		
15. **GANGWAY, CARGO AND COALING PORTS.**			
In ship's side and superstructures	none ✓		
16. **SCUPPERS AND SANITARY DISCHARGE PIPES.**			
Valves	Good ✓		
17. **SIDE SCUTTLES AND DEADLIGHTS**	Good ✓		
18. **GUARD RAILS**	Good ✓		
19. **PROTECTION AND ACCESS TO CREW'S QUARTERS.**			
Gangways	no gangways. ✓		
20. **LIFELINES** (fittings and material)	Good ✓		
21. **FREEING PORTS**			
Shutters	none ✓		
Protection bars	✓		
22. **TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.**			
Fittings or appliances	✓		
23. **ITEMS NOT INCLUDED IN THE FOREGOING**	✓		
24. **LOAD LINE MARKS**	Checked & found good ✓		

© 2020 Lloyd's Register Foundation