

FRI. NOV. 19 1920

No. 27980

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report

19

When handed in at Local Office

18 NOV 1920

Port of

Sunderland

No. in
Reg. Book.

Survey held at Sunderland

Date, First Survey

29 Oct.

Last Survey

17 Nov. 1920

on the Wood, Iron or Steel

Single screw steamer GLANMOR

Master

David Morris

TONNAGE:-

Built at Lowestoft.

By whom

Colby Bros

When 1920

MONTH

GROSS

Owners

Glanmor Shipping Co. Ltd

Port belonging to

Llanelli.

UNDER DEK

Owners' Address Burrows Chambers, Swansea.

NET

If not already recorded in Appendix to Register Book.

Surveyed Afloat or in Dry Dock? ☒ Afloat. Name of Dock

Destined Voyage

Warkworth.

WB=Cell DBor DBa

feet; uE&B

feet; f

feet; }

capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER.
* for Special Survey.
Date of last Survey and of
Periodical Surveys.Years
Actual
now
expired.Machinery and Boiler
Surveys
(including date of N.B., if any).

Report, No.

Port

Local Surveys, when held, must be reported in detail and acriation in the terms of the Rules. State clearly the nature and extent of Examinations and subsequent repairs. Repairs of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the movement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as

ft. ins.

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined?

Was a damage report made by anyone else? If so, by whom?

IRS, OR EXAMINATION AS PER RULE, FOR

Completion of Survey for Classification as

in Spanish Surveyor's letter dated 24th October 1920.

Port done. Portion of poop and main decks on port side fitted, riveted, caulked, holed, examined and found to be satisfactory. Portion of Engine and boiler casing on port side and casing top plates fitted, riveted, caulked where necessary. Engine room skylight and Storm covers to plating tops fitted, all satisfactory.

Equipment. Marks on Anchors compared, and found to agree with test Certificate.

At the request of the Engineer, examined decks when winches, windlance, capstan and steering gear were running, and found same satisfactory.

(P.T.O.)

ARY OF DAMAGE REPAIRS:-

Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

Renewed

Removed and Faired or Repaired

Faired or Repaired in place

NT CONDITION OF THE

Stringers

Inner Bottom Plating

State if Tanks have been examined inside

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

(State which.)

Rudder

Steering gear and its connections

Windlass

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Dblig. Plates under Soundng Pipes

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Caulking

Treennails

Breasthooks & Stemson

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shells ditto

Salting

(State if examined.)

Copper, or Y.M. of Wood Vessels

(State if on Felt.)

When put on, Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of 35. 15 Y 1 K.

Cables (State if now ranged)

" length size

(on board)

" Rule length size

Hawser & Warps

Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

The above work having now been completed satisfactorily, the vessel, is in my opinion, eligible for the class contemplated.

Fees (per Section 25) £

Fees applied for,

Damage or Repair Fee (if any) £

Received by me,

ling Expenses (if chargeable) £

10

Surveyor's Fee (if any) £

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

TUE. NOV. 30 1920

Character Assigned

Robert
Cargill & Co. Ltd

FRI. DEC. 24 1920

TUE. 11 OCT. 1921

FRI. 2 JUN. 1922

© 2020

Lloyd's Register

W511-0146

Is Certificate required? If so, to be sent to

WEB-FI
WEB-FI
WEB-FI
BRACK
Web I
BULK
V.T.BU
FRAME
COL
ARTI
ONGI
are the
are the
FLAT
(If Bar
GARBO
State
thick
wa. of
Det
THKNE
CLEAR O
Do. o
OBLG. of
Length
OOP SI
HOUT I
ORECA

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST, PER CERTIFICATE.				WEIGHT REQUIRED by TABLE 30 or 31.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Owts.	qrs.	lbs.	Owts.	qrs.	lbs.	Tons.	Owts.	qrs.	lbs.	Owts.	qrs.	lbs.			
35369	1st Bower	10	3	0	✓			12	13	✓	0	10	1		Stock 1st. Yellow.	Yellow Bros Ltd	Cradley Heath, 4-10-20 S.C. Paul.
35368	2nd "	10	2	14	✓			12	10	✓	3	10	1		"	"	6-10-20
35370	3rd "	8	3	20	✓			11	0	✓	0	8	3		"	"	4-10-20
	Collective Weight.	30	1	6								29	1				
35371	Stream	3	2	0	✓	0	3	4	5	18	✓	3	0		Ordinary	Yellow Bros Ltd	Cradley Heath, 4-10-20 S.C. Paul.
35428	Kedge	1	1	2	✓	0	1	8	3	13	✓	0	1	2	"	"	13-10-20

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.
35-0-8 34-1

CHAIN CABLES.

Number of Certificate.	Length and size supplied.		Test per Certificate.		WEIGHT OF CHAIN CABLE.		Length and size per Table 30 or 31.		Description.	Makers of Cables.	When and where tested and Superintendent.
	Length	Diam.	Statu- tory.	Breaking.	Supplied.	Per Table 30 or 31.	Length.	Diam.			
	Fathoms.	Ins.	Tons.	Tons.	Owts. qrs. lbs.	Owts. qrs. lbs.	Fathoms.	Ins.			
Iron Stream Chain or Steel Wire....											

Particulars of drop test of Cast Steel Anchor Leads.

Bower Anchor No 35369. ^{Cuts 4 1/2} 6-2-13. N.D. No 995. 11-6-20.
" " No 35368. 16-2-14. N.D. No 994. 11-6-20.
" " No 35370. 5-2-20. H.C.F. No 992. 21-7-20.