

Bag of plans in fixtures at end of alphabet.

1

Sent to Chief Surveyors 1/3/11.

Received from Chief Surveyors

VESSEL'S NAME *Stl. J. S. S. "Angora"*Report *Gls.*

No. 29791.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5/92.)

Nature of Survey

1st Entry When due

✱ 100A1 ("Steel") "Shade Deck"

2 Dks. (v Stl. Leaks) & Shade Deck (Stl. Leaks)

WB = all DBa 39' v EYB 125' f 110' 505t. FPT 56t. APT 64t.

FK. 6BH. com. Lloyd's A+C.P. Bow shade deck 190'

RM

R.H.
1/3/11



© 2020

WS12-0284

Register
Foundation