

of Ship Surveyor 1. 11. 17

Received from Chief Ship Surveyor

NAME Triple S.S. "MELITA".

Rpt. Gls. No. 37221


Notes of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Key

It is submitted the Belfast Surveyors should be informed that this vessel has proceeded to their port where the machinery will be fitted; and to complete the survey the poop deck requires to be tested, the watertight doors and pumping arrangements to be examined, and freeboard to be verified.

The Glasgow Surveyors should be requested to state whether the floors in the Cellular bottom are .48 to .42 as required.

  
2. 11. 17



© 2020

Lloyd's Register  
Foundation

WS13-0163