

Do. of
Do. of
Do. of
Do. of
Do. of
Do. of

1m.12.15.

Waverconie

now 'Imwacornie'
F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

17.6.18
Wm
Shells 'Palmol'

Rpt.

14pb

No. *15503*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

505

Depth "d"

Framing: Table No.

Description

Longitudinal Framing

Longitudinal No.

10605

Proportions

Length = *12.72*
Depth =

Upper Deck Sheerstrake

& other scantlings as approved for vessel.
built on the Longitudinal System

RETAIN

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100 A-1 (Steel)* *carrying petroleum in bulk* with freeboard, as recommended. The ~~summer~~ freeboard of *3.1* from centre of disc to top of statutory deck line at *upper* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

1 BH (Steel) & Web frames Longitudinal Framing

Cell DB. in E 34' 63E. D.T. 194E. FRT. 35E. APT. 66E

FK. 12 BH pl. com. Lysd. accp.

P 53' F 41'

fully asl-

WSR-0014

Lloyds Register Foundation