

Do. of
Do. of
Do. of
Do. of

Copy

Rpt. 12.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

(When received in London Office)

Port

Vessel's Name

Palmol

Official No.

No. in Reg. Book

Port of Registry (For Foreign Vessels)

~~Iron~~ or Steel

State whether Classed by Lloyd's Register

Yes

Name of Owners

Date of Verification

23 May 1918

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	3	ft.	1	ins.	<i>For all reasons</i>
From centre of disc to top of statutory deck line } at awning or part-awning deck }		ft.		ins.	
Fresh water line above centre of disc			<i>3 1/2</i>	ins.	
Indian Summer line above centre of disc			<i>-</i>	ins.	
Winter line below centre of disc			<i>-</i>	ins.	
Winter North Atlantic line below centre of disc			<i>-</i>	ins.	
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side	{	at main, spar or upper dk.	<i>Nil</i>	ins.	
		at awning or pt.-awning dk.		ins.	

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

S^r D. McAuslan Surveyor.

(To be filled up in London Office.)

Statement No. *25823* Date of Committee's Minute

22.5.18

Moulded Depth for record

16 ft. *6* ins.

Freeboards compared and found correct by

date

Is fee paid?

Form for Certificate

Instructions

date

Certificate written

Noted for posting

Drafted for record 13-6
Freeboard

*Compulsory freeboard
a condition of
classification.*

W518-0015



