

Length

Breadth

Depth

5c.5.25.

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *SSC So KAKARIKI.* Rpt. *Shul* No. *37147.*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

1st Long & Transverse
 Transverse No. *2850*

Depth "d" *12.45*Framing: Table No. *✓*Description *Bulb angle framing*

2nd Longitudinal No. *8787.5*

Proportions Length *13.66.*
 Depth =

Deck Sheerstrake *As approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *✠ 100 A.1 (stbl)*

✠ 100 A.1. (stbl)

1 dk (stbl)

*Cell DB & E 17' f. 123', 230t FPT 95t APT 28t
 FK, 3BH. *As approved* B53' F39*

Lloyds A & CP

Wichy aft:



© 2019
WMA
2.7.16

Lloyd's Register
 Foundation

WS19 0145