

FREEBOARD VERIFICATION FORM FOR TANKERS.

When received in London Office

Newcastle / Tyne

Nannah

No.

No. in Reg. Book *63533.*

Registry (For Foreign Ships)

Colon

Steel *Steel*

State whether Classed by Lloyd's Register *+100.F.I.*

of Owners

Date of Verification

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

	FREEBOARD AMIDSHIPS FROM TOP OF DECK LINE, <small>WOOD/STEEL DECK.</small>	FROM CENTRE OF DISC.
Tropical Fresh Water	<i>2</i> ft. <i>7 1/4</i> ins.	<i>10 3/4</i> ins. above
Fresh Water	<i>2</i> ft. <i>11 3/4</i> ins.	<i>6 1/4</i> ins. above
Tropical	<i>3</i> ft. <i>1 1/2</i> ins.	<i>4 1/2</i> ins. above
Summer	<i>3</i> ft. <i>6</i> ins.	
Winter	<i>3</i> ft. <i>10 1/2</i> ins.	<i>4 1/2</i> ins. below
Winter North Atlantic	<input checked="" type="checkbox"/> ft. <input checked="" type="checkbox"/> ins.	<input checked="" type="checkbox"/> ins. below

Summer Draught corresponding to the freeboard assigned as shown on Builders' Displacement Scales:—

Surveyor.

(To be filled up in London Office.)

Document No. *22908* Date of Committee's Minute


Particulars for Record Register Book.	}	Moulded Depth	ft.	ins.
		Freeboard	ft.	ins.
		Corresponding Draught	ft.	ins.

Freeboards compared and found correct by _____ Date _____

Fee paid? _____ Form for Certificate *L.L.R. - 30/9/1935.*

Instructions _____ Date _____

Certificate written *18/1/35* Noted for posting _____



© 2021

Lloyd's Register Foundation

WS24-0163