

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME STEEL S.S. "NUDDEA" Report G16. No. 38870.For the CHIEF SHIP SURVEYOR WILLIAM B. BROWN

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement" - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey _____

When due _____

The Downton Pump has been dispensed with for the present.

✱ 100 A.1. (steel) Shelter Dk. with freeboard.

2 Dks. (steel) & Shelter Dk (steel).

Cell DB 386' 1460t. DTA. 39' 1100t. FPT 125t. APT 80t.

FK. BBH to Shelter DK pt. comz Lloyd's A & C.R

P 31, F 43 on Shelter Dk.

W.B.B.

ass. 2020

7.7.19

Lloyd's Register
Foundation
WS25-0178