

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Rpt.

No. 25641

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

36.38

Depth "d"

12.16

Framing: Table No.

Page 10

Description

Single angle

Longitudinal No.

H729

Proportions

Length

9.62

Depth

Deck Sheerstrake 62 in line of 36 as required

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100A.1. ("Star") Steam Trawler as

recommended.

\pm 100A.1. ("Star") Steam Trawler

1 Dr

BK 7 $\frac{1}{2}$ HBH. Cum. Lloyd's 2060 Q73 F20



© 2020

Lloyd's Register
Foundation
W526-0280