

Lloyd's Register of Shipping.

(Report on Vessel No. _____ Port _____)

No. _____ SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned Iron or Steel Forgings or Castings, manufactured by Stavanger Electro Staalverk A/S. of Stavanger. for the Vessel No. _____, being built by Briksbergs Mek. Verkstads A/S. of Gothenburg have been inspected by me as set forth below and found to be, so far as can be seen, sound and free from defects.

Mark on Forgings or Castings.

Lloyd's
No. 1
S.A.E.

LLOYD'S
No 2
S.A.E.

S/S "Hure"

S. A. Eide

Bergen 7th. March 1923.

	STERN FRAME.	RUDDER FRAME.	STEM.
Material*	Steel by Electric process	Steel by Electric process	
How made	Cast	Cast	
Dimensions	RUDDER POST 140 ^{mm} x 76 ^{mm}	102 ^{mm} Dia. of main piece at top	
Progress on Inspection	Cast and rough condition	Cast and rough condition	
Date when Inspected	5. 3. 23.		
CASTINGS.			
Tests on Standard Test Pieces.			
Tensile Test—	Test No. 1 32.3.	Test No. 2 31.5.	
Tons per square inch	" " 30%	" " 30%	
Extension per cent. ...			
Cold Bending Test—	180° and no fracture	180° and no fracture	
Angle before fracture			
Drop Test—	Let fall from 45°		
Height from ground ...			
Hammering Test—	Yes	Yes	
If made according to Rules and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £ 2 : 16: 6.

To be paid at Stavanger.

* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.