

*Received from Chief Engineer Surveyor*

Yesspool

Rpt.

Leuco

No. 93167.

~~DAMAGE & WEAR AND TEAR.~~

General Exam<sup>n</sup>

SS No. 1 due 7.34, BS due 7.35.

A general exam<sup>n</sup> made of engines & boilers  
prior to vessel proceeding to Spain for  
breaking up.

It is submitted the vessel is eligible to remain as classed with *one-Push*  
record of Survey as recommended.

© 2021

✓ 2/12/35  
28-0344