

*Class is Subject to T.S. being examined before end of 10.36.*

Report to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME

*Winooska*

Report

*Lv.*

No. *106600*

**For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - (Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

*BB. + damage due to grounding*

When due

*10.35*


*Wolcott*

*Y. R. W.*

*24.1.36*

*Without special conditions*

*W5'29 - 015'8*



© 2020

Lloyd's Register  
Foundation