



LLOYD'S REGISTER

Greenock 6th October. 1920.

Upper Dk.	Dk.	Beam, Actual
Inches. Size in Ship.	Inches. Spacing in Ship.	

1

W/53

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. Turbine "MANIPUR". Report Grk. No 17709

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee, the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 34/5/02.

Nature of Survey

When due

✱100 A.1. (Steel).

2 Dks. (Stl.) and 3rd. Dk. (Stl.) in No. 1 hold.

Cell DB 422' 2018t. FPT 142t. APT 79t. DTa 1424t. DTf 1206t.

FK. 8 BH. Cem. Lloyd's A. & C.P. P76', B237', F86'.



2020
8. 10. 20.

Lloyd's Register
Foundation

W 53 - 0001

all ing.
two way of cargo
SS hold