

15 FEB 1938

Sent to Chief Surveyors 11-2-38

Received from Chief Surveyors

VESSEL'S NAME s.s. "Arankola" Report Cal No. 10070

## For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 2<sup>nd</sup> No. 2. When due 11,36  
 BS due 12,35  
 18 " 11,37

The 2nd S.S.No.2 became due 11,36.

The vessel was recently sold to Japanese buyers  
 to be broken up.

The case is fully stated in an endorsement dated  
 19th August last.

In reply to enquiry the Kobe Surveyors write to the  
 effect that the vessel is now lying in Osaka Harbour, but demolition  
 has not yet been commenced.

It is submitted for consideration whether a record  
 of "To be broken up" should not now be made in the Register Book.

PLATING to be DRILLED when  
 vessel is 24 years old,  
 or at next Special Survey  
 thereafter.

15.2.38



© 2019

Lloyd's Register  
 Foundation

WS'32-0004