

Remote

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel 56* "BRUNTON"

Rpt. *Ltk*

No. *15945*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *33*

Depth "d" *9.34'*

Framing: Table No. *3*

Description *Single angle as approved*

Longitudinal No. *4290*

Proportions  $\frac{\text{Length}}{\text{Depth}} =$  *12.38*

*Deck* Sheerstrake *as approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  100 A1 (steel) as recommended.

*1 Dk (steel). Well Dk*

*FPT 33t APT 16t*

*FK 3BH Asp Lloyd's A9CF Q 48' B8' F22'*

*Mchy aft*

*M* *acs*  
*14-6-21*



© 2019

Lloyd's Register Foundation

*WS'32-0205*