

F.E.

ved by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SEL'S NAME *St S K "HANNES RADHERRA* Rpt. *Hul* No. *36925*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long
Transverse No. *2250* Depth "d" *13.58*

Framing: Table No. *✓* Description *angle frames as approved.*

2nd Longitudinal No. *6075*

Proportions $\frac{\text{Length}}{\text{Depth}} =$ *10*

Deck Sheerstrake *as approved*


Revised Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A.1. (Steel). Steam hauler.
1 Dk.
Cell D.B. 22' 27".
B.K 8", H B.H, Cem, Lloyd's A + CP.
Q 84', F 25'.

[Signature]
[Signature] 26

It is concluded the thickness of the sheerstrake and the strake below are as approved and not as shown ~~in~~ ^{all} the first entry report.



© 2020
Lloyd's Register
Foundation
WS 5-0188