

FREEBOARD VERIFICATION FORM FOR STEAMERS CARRYING TIMBER DECK CARGOES.

Signal letters
L. I. T. R.

When received in London Office

Port Oslø Name Lysaker III 1167 tons
Official No. ✓ No. in Reg. Book Oslø
Port of Registry (For Foreign Ships) Oslø
Iron or Steel _____ State whether Classed by Lloyd's Register _____
Name of Owners _____ Date of Verification _____

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

ORDINARY CARGO ^{AND} _{OR} PASSENGER SHIPS.

Freeboard amidships from top of deck line, wood/steel deck.

From centre of disc.

Tropical Fresh Water	ft.	ins.	ins. above
Fresh Water	ft.	ins.	ins. above
Tropical	ft.	ins.	ins. above
Summer	ft.	ins.	
Winter	ft.	ins.	ins. below
Winter North Atlantic	ft.	ins.	ins. below

SHIPS CARRYING TIMBER DECK CARGOES.

Freeboard amidships from top of deck line, wood/steel deck.

From centre of disc.

Tropical Fresh Water Timber	97.8	3	ft.	2 1/2	ins.	444	17 1/2	ins. above
Fresh Water Timber . . .	107.3	3	ft.	6 1/4	ins.	349	18 3/4	ins. above
Tropical Timber	107.9	3	ft.	6 1/2	ins.	343	13 1/2	ins. above
Summer Timber	117.5	3	ft.	10 1/4	ins.	247	9 3/4	ins. above
Winter Timber	130.1	4	ft.	3 1/4	ins.	121	4 3/4	ins. above
Winter North Atlantic Timber	154.3	5	ft.	0 3/4	ins.	121	4 3/4	ins. below

Maximum Summer Draught corresponding to the freeboard assigned as shown on the Builders' Displacement Scales:—

Surveyor.

(To be filled up in London Office.)

Statement No. 30752 Date of Committee's Minute _____


Particulars for Record in Register Book. { Moulded Depth ft. ins.
Freeboard ft. ins.
Corresponding Draught ft. ins.

Freeboards compared and found correct by _____ Date _____

Is fee paid? _____ Form for Certificate _____

Instructions _____ Date _____

Certificate written 27/12/38 Noted for posting _____



© 2020

Lloyd's Register
Foundation

W536-0286