

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Newcastle

When received in London Office

Name "St. Agnes"

118316

No. in Reg. Book

64

Registry (For Foreign Vessels)

Steel

State whether Classed by Lloyd's Register

Yes

Owners

Date of Verification

I have to report that the Freeboard from the centre of disc to the top of the deck line, and the lines in connection therewith, as given below, assigned committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

Centre of disc to top of statutory deck line	1	ft.	4½	ins.
Centre of disc to top of statutory deck line		ft.		ins.
at awning or part-awning deck				
High water line above centre of disc			4	ins.
Mean Summer line above centre of disc			2½	ins.
Winter line below centre of disc			2½	ins.
Winter North Atlantic line below centre of disc			5½	ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side			1½	ins.
				ins.

It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

to to hwc tonight
NRS 7.6.06

Surveyor.

(Filed up in London Office.)

No. Date of Committee's Minute

Depth for record ft. ins.

is compared and found correct by date

Form for Certificate

date

written

7.6.06

Noted for posting

W538-0294

percentage
12, or 13.)

56.8%

© 2021

Lloyd's Register
Foundation