

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Steel S.S. "EMLYNTON". Rpt. Lon. No. 84041.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 40.8.

Depth "d" _____

Framing: Table No. 3 Description Single angle as approvedLongitudinal No. 7233.Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.2}{}$ Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * 100 A.1. (Steel) as recommended.

1 Dk. steel. Well Dk.

Cell.D.B.f 103'., 172t., FPT.85t., APT.35t.

FK., 3BH., Cem., Lloyd's A.& C.P., Q 114'., F 23'., Machy.aft.

Date of Build 12.20.

The approved ~~plans~~ rudder plans &c., should be forwarded with the report on the Sister Vessel.

© 2020
22. 2. 21.Lloyd's Register
Foundation

W542-0014