

Kambove n. n. MARZOCCO

Received from Chief Surveyors

VESSEL'S NAME *Sheless War Argon* Report *Sl.* No. *38317*

For the **CHIEF SHIP SURVEYOR** and ~~CHIEF ENGINEER SURVEYOR.~~

A broken unit in No 2 deep tank requires to be renewed & the  
Surgeon states in these opinions, the renewal of same may be left  
to the Chinese representatives.

\* 100 A-1. (Steel) Carrying oil fuel in bulk F.P. above 150°F

15% (Sheet)

Cell 5B. a 35' u E+B 42 + 85' 4306. FRT 1276. CRT 916

13-39  
Lloyd's Register  
11-18  
Foundation  
WSS-0056

W55-0056

BEAMS, Upper Deck, ~~Single Angle~~, Bulb)

	• 42			• 42	
10	$3\frac{1}{2}$	• 46	10	$3\frac{1}{2}$	• 46

Tie Plates, outside Hatchways.....

Deck.\* Material and thickness

**Fourth and Fifth Deck Stringer Plate.**

breadth & thickness