

Good order cleaned and painted; Hatch, Cabin

1800, 12, 19,

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "HIGHLAND WARRIOR". Report Liv. No. 82031.

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the extent or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

Condition

When due _____

Noted.

W.P.W.

19.3.21

M

Without special



© 2021

Lloyd's Register
Foundation

W55-0193

survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss 216, 1-10 and para 210, 20.

This vessel is now so far as seen in good