

1

W.142

"Maryad"

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl Se VITRUVIA Report Snk No. 18536**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey 1st Entry When due _____

✱ 100 A. I. (Steel). Carrying Petroleum in Bulk

2 D^{ks} (Stl) + web frames, Longitudinal framing.

cell D.B. E + B 60 1235, A.P.T. 815

F.K., 11BH to upper DR. 5 B.H. to 2nd D^k, pt Cen, Lloyd's A.C.P.

P108', B 35', F 51'. "machy aft"



© 2019

Lloyd's Register

52-0152 Foundation