

F.E.

by Chief Ship Surveyor 7.8.13

Received from Chief Ship Surveyor

EL'S NAME Sheelss Kathlamba

Rpt. Hpl

No. 14706

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 34/5/92.)

Transverse No. 88.24

Depth "d" 19.7

Framing: Table No. 3 page 15

Description Bulb angle as approved?

Longitudinal No. 38282

Proportions Length = 10.24
Depth =

Bridge Deck Sheerstrake 10 in excess of Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \star 100A-1. (Steel) as recommended.

\star 100A-1. (Steel)

2 DKs (Steel)

WB = Cell & B. a 159' u r x B 42' + 183' 1450 t. DTA ^{24'} 793 t

FK. 7 BA. Cem. Lloyd's aver. P 77. B 155' F 81.

sheelss



© 2021

Lloyd's Register Foundation

W561-0009