

5c.12.16.

F.E.

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME Steel S.S. "JINSHO MARU". Rpt. Kob. No. 1948

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 71.

Depth "d" ✓

Framing: Table No. -

Description Longitudinal framing.

Longitudinal No. 21655

Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{8.9}{1}$

Bridge Deck Sheerstrake and other scantlings as approved for vessels built on the Longitudinal System.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 AL. (Steel) as recommended.

2 Dks. (Steel) & Webframes. Longitudinal Framing.

Cell DB 255' 518t. FPT 76t. APT 20t.

EK. 5 BH. Cem. A. & C.P. P19', B82', F32'.

21. 5. 19.



© 2020

Lloyd's Register  
Foundation

W563-0083