

RETAIN

F.E.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel S.S. "SKÜLI FÓGETI" Rpt. Hol. No. 31801

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

Reverse No. 38.83 Depth "d" 12.42'

Long: Table No. 3 Description Single angle as approved.

Longitudinal No. 5436

Proportions $\frac{\text{Length}}{\text{Depth}} =$ 10.12

~~Deck~~ Sheerstrake .625" instead of .4" as required.

This vessel appears to have been built in accordance with the
and the approved plans, and it is submitted she is eligible to
be classed ☒ 100 A.1. (steel) "Stm. Trawler" as recommended

1 Dk.

DB. Bunkers 21' 24t.

BK 7½. 4BH. Cem. Lloyd's A7C.P. R79, F22.

It is concluded the Double Bottom tank has been tested as required
The Surveyors should be requested to state if this is on

Lloyd's Register
Foundation
W563-0097