

5m, 11, 28.

4 JUN 1929

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl. S.S. "SAIGON MARU".Rpt. Kob. No. 6507.**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ture of Survey _____


The Kobe Surveyors report this vessel placed in dry dock, bottom cleaned and coated, 3 shell plates renewed and 2 partly doubled, 8 deck plates renewed and 90 fathoms of chain cable placed on board.

It is submitted the vessel appears worthy to remain as classed, with record of survey 5,29, as recommended.

100 A. 1

Kob. Rⁿ

5.29 Kob.

© 2021

Lloyd's Register
Foundation

WS83-0020