

Undertaking base.

-1 AUG 1935

Chief Surveyors 26. 7. 35

Received from Chief Surveyors

SHIP'S NAME *7 Comte de Flandre*

Report Ant

No. 18993

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/32.)

Class of Survey 2nd S.S. No 3

When due 7.31

*Note: Another Special Survey due 7.35*

The class is subject to the outer plates (E.W. 5,31) being specially examined at the next dry docking.

The 2nd S.S. No.3 became due 7,31 and no part of the Survey has been held.

The vessel being laid up the Owners have furnished the usual undertaking.

The vessel was generally examined in August 1933 and found satisfactory (Special Survey more than 2 years overdue).

The case received consideration in September last (Special Survey more than 3 years overdue), but a further general examination was not then required.

The Antwerp Surveyors wrote on the 3rd instant that the vessel was still laid up.

(Another Special Survey has now become due.)

It is submitted for consideration whether another general examination should now be asked for.



29 30 2020

Lloyd's Register  
Foundation  
W585-0123