

1.

Comtesse de Flandre

Sent to Chief Surveyors 19. 3. 07

Received from Chief Surveyors

VESSEL'S NAME *Ste. S. S. "Bankdale"*Report *Es.*

No. 14991

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

When due

+ 100 A 1 ("Steel") *Spar deck*

1 DR (Ste) + Spar DR (Ste) + deep framing.

H. B = Cell DB a 128' u E + B 44' f 152' 953t DT a 36' 815t FPT 97t APT 51t

FK 68H Cam. *Leopoldi* AXCP P 37' B + F 298'C. H. p
19/3/07

© 2020

Lloyd's Register
Foundation

W585-0191