

S.S. "SAN EDUARDO"

The 2nd S.S.No.2 became due in 9.33 and a report has been received from the Liverpool Surveyors of an examination made with a view to enabling the approximate cost of the work in connexion with this Special Survey to be ascertained. The Surveyors conclude their report by stating that after obtaining an estimate of the cost of the work the Owners decided to sell the vessel for breaking up.


According to Lloyd's Index the vessel arrived in the Clyde on 13th instant for breaking up.

It is submitted the vessel might be posted accordingly in the Register Book.

RB
21.3.34

*For Mr. Spinks to
write G.R.*

21. 3. 34



© 2020

Lloyd's Register
Foundation

Whole
has to
d (if ass
and now
m?
use
in
into
and
for
ref
ms:—
Copper, c
(Sta
When
Boats ...
Masts, Y
Conditio
(Stat
Sails.....
Equipm
Anchors
Cables
" I
" I
Hawser
Standin