


# — M.V. CHALLAMBA. —

SHOWING VARIATION  
IN LINE OF KEEL

SHOWING TWIST TO PORT  
ON DRYDOCK. JULY 1<sup>st</sup> 1927

AT ESQUIMALT.

LEFT HAND FIGURES SHOW  
TWIST AFTER UNDOCKING.  
JULY 5, 1927



GARBOARDS SHOWN  
HOG OF  $3\frac{3}{4}"$  AT  
MIDDLE OF LENGTH

TOP OF STEM OVER  
TO PORT  $5"$  IN FULL  
DEPTH OF STEM.

← BEAM.  $44'-6"$




S.S. Challamba.

Vcr report no 1889

Sketch shewing  
extent of damage.

---



© 2021

Lloyd's Register  
Foundation

W592-0141