

Last Report No. 1000  
Particulars of Examination and Repairs (if any) Damage £1000 + 100 Adm. Fee

2m,4,31.

The class is subject to the engines & boilers being further examined on arrival at Antwerp.

5E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME Dimitrios L. Kamolos Rpt. Acc. No. 19410

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.

Nature of Survey

DAMAGE & WEAR AND TEAR. Through collision & beaching.

DBS due 11.33.

The vessel is proceeding to ready for demolition, and in the circumstances the DBS has not been held, but a general examination has been made of the engines & boilers.

No immediate action be deferred.

Lly  
29/6/34.

~~It is submitted the vessel is eligible to remain as classed with record of Survey as recommended~~



© 2021

Lloyd's Register  
Foundation

W896-0160