

Dredger "Balbus".

At the request of Captain R. P. R. Taylor, Surveyor to Lloyd's Register, Rangoon, I, the undersigned, periodically attended onboard the above vessel during construction of same at Dalla Dockyard when I examined ship's side connections, bilge pipe arrangements, fuel oil and lubricating oil installations, and all electrical equipment, and have to report that all work has been carried out to comply with Lloyd's requirements. On completion of above work trials were carried out and proved very satisfactory. I consider this dredger to be well fitted out and a first class job.

No. of visits:- Six.

B. I. S. N. Coy. Ltd.

DEPUTY SUPERINTENDING ENGINEER.

B. I. S. N. Coy. Ltd.

Rangoon.

30th August, 1934.



© 2019

Lloyd's Register
Foundation

W6-0113