

2500, 12, 19.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel S. S. "NATIA"

Report

Gls.

No. 40673

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.6.02.)

Nature of Survey

When due

Repairs have been effected to damage sustained by fire.

100 A.1. (steel) "Shelter Dk. with freeboard"

3 Dks (steel) & Shelter Dk. (steel - w.s.).

Cell DB 386' 1221t. FPT 120t. APT 65t

FK. 4BH to Shelter Dk. 3BH to upper Dk. Com. Hlyds' A1CP

Date of Build 12, 20.

B 227', F 37' on Shelter Dk.



2020

17-12-20

Lloyd's Register
Foundation

W 60-0126

In Register Book.

Corresponding Draught

29

ft.

3

ins.