

1

Sent to Chief Surveyors 8.11.17

Received from Chief Surveyors

VESSEL'S NAME

L. S. Actor

Report

Sl

No. 37234

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

When due

✱ 100 A.1 (Phil)

2 Dk (Phil) 3<sup>rd</sup> Dk (Phil) - No 1. Hull

Cell DB 344 1117E. D.T. a 31' 830G. F.P.T. 64E. A.P.T. 46

FK 7 BH. Cen. Long arc. P34 B 139' F53

Carrying oil fuel F.P. above 150° F in double bottom.

8.11.17



© 2020

Lloyd's Register  
Foundation

UK 60-0178