

Chief Surveyors _____

Received from Chief Surveyors _____

NAME Steel S.S. "CITY OF ALEXANDRIA" Report Two No. 81859

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey _____ When due _____

Downton pump has been omitted for the present but it is understood
Owners will fit same if required
10 A-1. (Steel)

Dks (Steel v. os.) & web frames, "Well Deck"

all DB 301' 762t

PK 734, Cen, Rlyths Av CP. P & B 226' F40'


Date of Build 1905

S.S. No: 1-21-1, 21

1-21 No.

Subject to rawse pipes
being repaired

PLATING to be done on upper vessel
is 24 years old. At next special
survey thereafter.



© 2020

Lloyd's Register
Foundation
11601-0133