

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl S "US WORTH" Rpt. Sld No. 29327

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/3/02.)

1st Long

Transverse No. 9223

Depth "d" 22.87

Framing: Table No. ✓

Description Bull angle frames as approved.

2nd Longitudinal No. 26461

Proportions Length 13.73
Depth =

Deck Sheerstrake as approved

Revised Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A.1. (Steel)

1 D" (Stl).

Cell D.B 312' 813t, F.P.T. 70t, A.P.T. 111t.

F.K, 6 B.H, pt Cem, Lloyd's A. CP.

P 34', B 108', F 32'.

6.12.26



© 2021

Lloyd's Register

W605 Foundation