

1.

Sent to Chief Surveyors 30. 6. 03

Received from Chief Surveyors

VESSEL'S NAME *See S.S. "Mercury"* Report *Sub* No. 13661

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, (24/5/92.)

Nature of Survey

*First entry**When due*

+ 100 A 1 ("Stub") Spar bulk

1 DR (see) & spar DR (see) & deep framing.

W.B. - Cell DB a 112' a ETB 40' f146' 8996 DT a 36' 816t APT 716

FK 6BH Am. Ployd A & CP P 20' B 203' F 37'

C. H. J.
30/6/03

© 2021

Lloyd's Register
Foundation

W608-0183

FIDELITY, IN EACH ROOM, DEDUCTION

" Hold
Quarter, 'tween Dks., "

48 48
22 96
22 96

" Deck, Material and thickness *STEEL*
Forecastle Deck Stringer Plate, b'dth & th'kns
" Angle on ditto

30
3 x 3