

pt. 6.

For the information of Surveyors and the Committee only.

Received at

14 MAY 1925

Office

10

Lloyd's Register of Shipping.

(Report on Vessel No. 36664

Port

Hull

s/s Venari

No. F.19192. SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~Iron~~ ^{Scrap} or Steel Forgings or Castings, manufactured by Messrs Emerson Walker & Thompson Bros Ltd of Dunston-on-Tyne for the Vessel No. 473, being built by Messrs Cook Weldon & Gemmill Ltd of Beverley have been inspected by me as set forth below and found to be, so far as can be seen, Sound.

Mark on Forgings or Castings.

Lloyd's

No. 72684

JD

11.5.25

J Dale
Newcastle.

STERN FRAME.

RUDDER FRAME.

STEM.

Material*

How made

Dimensions

Progress on Inspection

Date when Inspected

CASTINGS.

Tests on Standard Test Pieces.

Tensile Test—

Tons per square inch

Extension per cent. ...

Cold Bending Test—

Angle before fracture



Drop Test—

Height from ground ...

Hammering Test—

If made according to Rules and found satisfactory ...

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.



Fee (if any chargeable) £

To be paid at

* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.