

Do. of B. Qr. Dk.
Do. of Bridge House

Deduct height of 'tween deck when this does not exceed 8ft.

48.5

When built 1908

Sm.12.10.

ORIGINAL

Inspected by Chief Ship Surveyor 2/7/11

Received from Chief Ship Surveyor

VESSEL'S NAME *M J S 'Leopoldville'* Rpt. *Aut* No. *9354*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Character of Survey *First entry*

This vessel was built by Messrs. Harland & Wolff in 1908 but not under the supervision of this Society's, or any other Society's Surveyors,


Sketches of the midship section and profile were recently forwarded to this Office by Lord Pirrie and a request was also received from the Owners for the vessel to be classed in this Society's Register.

The scantlings and arrangements were carefully compared with the requirements of the Rules and found to be such as could be recommended to the Committee for approval for the class 100A "Shelter Deck".

A report has now been received from the Antwerp Surveyors from which it appears that the scantlings of the vessel have been verified and the requirements of Section 48 of the Rules complied with.

The equipment of anchors, cables, hawsers and warps etc. is also in order.

It is submitted for the favourable consideration of the Committee that the vessel appears worthy to be classed 100A, "Shelter Deck with freeboard", The Summer freeboard of 12 feet 1 1/2 ins. from centre of disc to top of statutory deck line at Shelter deck,



SPARS, BRIDGE DECK, Angle, Dumb Angle, Plate, Tee Bulb or Channel	<input checked="" type="checkbox"/>	Bridge Deck Stringer Plate, br'dth & thickness	<input checked="" type="checkbox"/>	Angle on ditto	<input checked="" type="checkbox"/>				
---	-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------	-------------------------------------	--	-------------------------------------	----------------	-------------------------------------

now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further the remaining freeboards as shewn on the accompanying verification form to be inserted in the certificate of classification, and a record of survey and notation of S.S. Ant. 11 should be assigned.

100A.1 (2nd) Shutter and with freeboard.

2nd (2d) & Shutter on (2th - Jean 5)

WB. 600 073104 u 3 0737i + 160 8396 FPT 606 APT H66

FK. 6 BH "After plan to 2nd on only" 6m Lloyd's at 60

P on Shutter on 57 & F on Shutter on 53

7-11 Ant

St Ant WT-11

E. E. E. E.
RBA
2nd 7/11



© 2020

Lloyd's Register
Foundation

WB12-0200 3/2