



Lloyd's Register of British & Foreign Shipping,

HEAD OFFICE: 71, FENCHURCH STREET, LONDON, E.C.

LLOYDS REGISTER,
LONDON.

REC'D 7 JUN 1910

ANS'D 9

Vienna ^{IV}/₂

Schelleingasse 52^{IX}

4th June 1910

D

M. KOCH,
SHIP AND ENGINEER SURVEYOR.

The Secretary of Lloyd's Register

London

Sir

I am in receipt of your favour of 30th May and of the enclosed photograph as well regarding the cast steel rudder of the S. S. Galileo, and in reply thereto I beg to say the great defect now discovered through destroying of the rudder shows surely great carelessness on the part of the Skodawerke in making this casting, and I am really surprised that after the drop test this fault did not show.
Enclose the photograph.

I am, Sir,

your obedient servant

M. Koch



© 2020

Lloyd's Register
Foundation

W619-0021

Lloyd's Register of British & Foreign Shipping

HEAD OFFICE: 21, FENCHURCH STREET, LONDON, E.C.



LLOYD'S REGISTER
LONDON.
REC'D JUN 1910
ANG 7

Vienno 17

4 June 1910

Schellinggasse 25 IX

The Secretary of Lloyd's Register

London

M. KOCH,
SHIP AND ENGINEER SURVEYOR.

Sir

I am in receipt of your favour of 30th May and of the enclosed photographs as well regarding the cast steel rubbing of the S. S. Galier, and in reply thereto I beg to say the great defect was discovered through abetting of the rubbing when only great carelessness on the part of the workmen in making this casting, and I am really surprised that after the history this fault did not show. I enclose the photograph.

Referred to the Chief Ship Surveyor,
and the Chief Engineer Surveyor.

Wm. H. H. H. H.

Referred to Mr. Beaumont

JUN - 7 1910

Wm. H. H. H. H.



© 2020

Lloyd's Register
Foundation

Weld-0051