





Sketch showing defects in the cast steel
single plate rudders of the S.S. "Galileo."



© 2020

Lloyd's Register
Foundation

W619-0031