

m.321.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "Cleander"

Rpt. *Cff*

No. 43660

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 90.29

Depth "d" 24.04

Framing: Table No. 1

Description Longitudinal Framing

Longitudinal No. 38,825

Proportions

Length = 12.82 to upper Dk
Depth

and odd scantlings
Upper Deck Sheerstrake, as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to

be classed *100A1 (Steel) "Carrying petroleum in bulk."
2 Dks (Stl) + web frames, "Longitudinal Framing."
Cell DBu B41, 104t, DTf 40', 689t, F.P.T. 58t, A.P.T. 43t,
FK. 18BH (10BH to upper Dk, 8BH to 2nd Dk) pt. Cem
Lloyds A+C.P. P109 'B32' F52'
Machinery aft.



Lloyd's Register
Foundation

W63-0057