

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME *Alt Tuni Se "FORT VICTORIA"* Report *N. YK* No. *30986*

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

Condition

When due _____

*Subject to indented plating being dealt with at
Owners' convenience.*

[Signature]

NAB

4-1-30

Shelter dk with iceboard.



© 2019

Lloyd's Register
Foundation

W64-0030