

F.E.

ved by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME *Steel S.S. "CRAIGAVON"*

Rpt. *Dublin*
9/2

No. *4113*
11245

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *42.00*

Depth "d" *14.42*

Framing: Table No. *3*

Description *Bull angles as approved*

Longitudinal No. *7560*

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{10.43}{1}$

~~Deck~~ Sheerstrake *as approved*

Survey completed at Glasgow

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

100.A.1. (Steel)

1 Dk (Steel) "Well Deck"

Call DB 103' 176t, FPT 80t, APT 28t

FK, 3BK, Cam, Hlyths Av CP, Q108' B12' F30' Mchly aft

M
9.9.11



© 2019

Lloyd's Register
Foundation