

Eng
Gross
Less
Less
Eng
TONN.

Loriso

F.E.

Received by Chief Ship Surveyor 1.8.01

Received from Chief Ship Surveyor

VESSEL'S NAME *S.S. "Monomoy"* Report *Sd.* No. *20629*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	✓	✓
Spar Sheerstrake . .	✓	✓
Description of Framing:— <i>Zed.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100 A1 ("Steel") *Shelter Deck* as recommended.

\pm 100 A1 ("Steel") *Shelter Deck*

2 DR (Sd) 3 1/2 B & web frames, & Shelter DR (Sd)

W. B = Cell DB a 113' a E & B 50' f 167' 1053t DT a 36' 977t DT f 44' 1295t

FPT 108t APT 34t

FK 7 BH Cam. A & CP

C. X. J.
1/8/01



© 2020

W642-0046
Lloyd's Register
Foundation