

Compulsory

Rpt. 12.

19971

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Port *Newcastle on Tyne* When received in London Office

Vessel's Name *S/S Harford*

Official No. _____ No. in Reg. Book *25 (Supl.)*

Port of Registry *(For Foreign Vessels)* _____

Iron or Steel *Steel* State whether Classed by Lloyd's Register *To be*

Name of Owners *J & C Harrison* Date of Verification *16.12.08*

I have to report that the Freeboard from the centre of disc to the top of the statutory deck line, and the lines in connection therewith, as given below, assigned by the Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

From centre of disc to top of statutory deck line	3	ft.	$6\frac{1}{2}$	ins.
From centre of disc to top of statutory deck line		ft.		ins.
at awning or part-awning deck				
Fresh water line above centre of disc			$6\frac{1}{2}$	ins.
Indian Summer line above centre of disc			$5\frac{1}{2}$	ins.
Winter line below centre of disc			$5\frac{1}{2}$	ins.
Winter North Atlantic line below centre of disc				ins.
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side	at main, spar or upper dk.		$1\frac{3}{4}$	ins.
	at awning or pt. awning dk.			ins.

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

*Classification 100as Shelter Deck
conditional on above freeboards*

(Sgd) Alex. Munro Surveyor.

(To be filled up in London Office.)

Statement No. _____ Date of Committee's Minute _____

Moulded Depth for record _____ ft. _____ ins.

Freeboards compared and found correct by _____ date _____

Is fee paid? _____ Form for Certificate _____ date _____

Instructions _____

Certificate written _____ Noted for posting _____

Im.11.6. 2.



© 2021
Lloyd's Register
Foundation

W057-0171

Committee's Minute

Character assigned

FRI. 15 JAN 1909

100as