

Rpt. 6.

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of British & Foreign Shipping.

(Report on Vessel No. Port)

No.

SHIP FORGINGS ~~OR CASTINGS.~~

I have to report that the undermentioned ~~Iron or Steel Forgings or Castings~~, manufactured by R. S. Bagnall & Sons Ltd. of Hylton for the Vessel No. 149, being built by Osborne Graham & Co of Hylton have been inspected by me as set forth below and found to be, so far as can be seen, Sound

Mark on Forgings or Castings.

Lloyd's

No. 5981

MR

M. Robertson

Built Panduland, 4-2-14

STERN FRAME.

RUDDER FRAME.

STEM.

Material* ...

How made ...

Dimensions ...

Progress on Inspection ...

Date when Inspected ...

CASTINGS.

Tests on Standard Test Pieces.

Tensile Test—

Tons per square inch ...

Extension per cent. ...

Cold Bending Test—

Angle before fracture ...

Drop Test—

Height from ground ...

Hammering Test—

If made according to Rules and found satisfactory ...

Scrap steel
forged
5 3/4" dia to 4 1/4"
Forged & Finished
22.12.13 to 30.1.14

JH

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £

To be paid at



© 2021

Lloyd's Register
Foundation

* If of Iron, state whether scrap or puddled Iron. If of steel, state whether made on the Open Hearth process.