

Received from Chief Surveyors _____

Surveyors _____

NAME Steel S.S. "Elizabeth"

Report N. Ns.

No. 3609

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Copy First Entry. When due _____

was built in 1919 at Wilmington & classed with the American Shipping
have been approved by the American Committee for the Class 100A1

1 (Stl)

Stl) & Web frames. Longitudinal Framing

B. 232' 666t

FPT 78t

APT 282t

7BH. 7t Cem.

P 26' B 98' F 37'


of Build 1919.

22 N. Ns.

N. Ns N° 3-7-22

subject to chain cables and
anchors being verified with
the certificate when produced
and found in accordance
with the weights as approved.

W660-0013



© 2021

Lloyd's Register
Foundation

RKM
7.9.22